

GOVDOC


BRA

599

vol. 2

pt. A

BOSTON
PUBLIC
LIBRARY



BRA
599
Vol. 2
part A ✓


HYNES AUDITORIUM EXPANSION

BOSTON, MASSACHUSETTS

Final Report (Volume II – Part A)

Support Documentation

Architectural Reconnaissance Survey



CITY OF BOSTON
Kevin H. White, Mayor

BOSTON REDEVELOPMENT AUTHORITY
Robert J. Ryan, Director

PUBLIC FACILITIES DEPARTMENT
Donald B. Manson, Director

Back Bay
B65M
1982

Support Documentation

Architectural Reconnaissance Survey

Kallmann, McKinnell & Wood, Architects, Inc.

Final Report (Volume II – Part A)

Support Documentation

Architectural Reconnaissance Survey

Table of Contents

Introduction

Basement Floor

Mezzanine

First Floor

Second Floor

Third Level

Stairs

Escalators & Elevators

Exterior

ARCHITECTURAL RECONNAISSANCE SURVEY

INTRODUCTION

The following survey is the end result of an extensive on-site, room by room, inspection of the existing Hynes Auditorium conducted by Kallmann, McKinnell & Wood, Architects, Inc. in the reconnaissance stage of the design process.

The survey consists of four major groupings:

- . Rooms
- . Stairs
- . Escalators and Elevators
- . Exterior

Rooms:

Each room has been documented in terms of the materials employed, their location and condition. Organized by level, a corresponding floor plan indicating the room's number and location precedes each level grouping.

Stairs:

Stairs and their enclosures have been documented in materials used, their location and condition, similar to that of the rooms.

Escalators and Elevators:

Defined by manufacturer type, capacity, speed and condition.

Exterior:

Exterior elements, doors, walls and roofs forming the enclosure of the existing facility have been defined by material, location and condition.

ARCHITECTURAL RECONNAISSANCE SURVEY

SUMMARY

The Hynes Auditorium, a facility consisting of four levels and some 326,000 sq. ft. was completed in 1965. Time and the lack of maintenance have taken their toll on this seventeen year old facility, both internally and externally.


Internally, whatever maintenance has occurred appears to have been limited to the public spaces of the facility, although even these spaces are in need of general repair. Doors and their hardware represent the areas requiring the greatest amount of attention. It is, however, in the support spaces (those not used by the general public) that the lack of maintenance is most prevalent. The removal of toilet partitions, water closets, sink hardware, toilet accessories and door hardware would seem to indicate that these support spaces are the areas from which replacement parts needed in the public spaces are obtained. Inoperative water fountains, leaking urinals and water closets, walls with broken and missing glazed block, soot covered and missing ceiling tile, broken and sometimes missing light fixtures, missing sections of wall base and tile flooring place the existing facility in need of a major upgrading.

Externally, it is in the roof area that the bulk of required work occurs. With the gravel ballast almost completely absent, flashing and gravel stops in poor condition and a generally spongy quality to the overall roof surface, it would seem as though a complete re-roofing of the facility is in order. Additionally, a large portion of the exterior doors and door frames have reached a point of deterioration requiring replacement.

Architectural Reconnaissance Survey

Basement Floor

Kallmann, McKinnell & Wood, Architects, Inc.



BASEMENT PLAN

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME OFFICE

ROOM NO. B05

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T. & Carpet	Poor	Lighting fixtures are in poor condition. Existing walls have been faced with sheets of cardboard. Therefore unable to determine condition of walls.
BASE	None		
WALLS:			
North	Concrete		
East	C.M.U.		
South	C.M.U.		
West	C.M.U.		
CEILING	Perf. Metal Tile	Poor	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME CLOSET

ROOM NO. B06

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Approximately half of the ceiling tile is missing.
BASE	None		
WALLS:			
North	Concrete	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Perf. Metal Tile	Poor	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME OFFICE

ROOM NO. B08

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Poor	Tiles are missing from floor. Base has been removed. Door needs to be replaced.
BASE	None		
WALLS:			
North	Painted Concrete	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U. & Concrete	Good	
CEILING	Perf. Metal Tile	Good	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME MEN

ROOM NO. B09

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Minor cracking in one terrazzo panel. Some cracking in plaster ceiling. Extensive corrosion of toilet partitions.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Plaster	Fair	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME PAPER BALING ROOM

ROOM NO. B10

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	This room has been converted to a refrigeration room and presently used by Hub Catering Co.
BASE	None		
WALLS:			
North	Plywood	Good	
East	Plywood	Good	
South	Plywood	Good	
West	Plywood	Good	
CEILING	Plywood	Good	
DOOR(s)	Plywood	Good	
DOOR FRAME(s)	Wood	Good	

ROOM NAME FOOD CONCESSION STORAGE

ROOM NO. B11

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Wd.Stud/Masonite	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed	Good	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME LIQUOR STORAGE

ROOM NO. B11A

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	This room has been added since original building.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Wd. Stud/Masonite	Good	
West	Painted C.M.U.		
CEILING	Exposed	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME LOADING PLATFORM

ROOM NO. B12

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Fair	Platform floor has a lot of minor cracking. Some cracking in C.M.U. of north wall. Damage at elevator entrances due to missing guards.
BASE	None		
WALLS:			
North	Pn'td.Conc./C.M.U.	Fair	
East	Painted C.M.U.	Fair	
South	Painted C.M.U.	Good	
West			
CEILING	Exposed	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME TRUCKING AREA

ROOM NO. B13

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Some minor cracking in C.M.U. of west wall.
BASE	None		
WALLS:			
North	Painted Concrete	Good	
East			
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed	Good	
DOOR(s)	Hollow Metal	Good/Fair	
DOOR FRAME(s)	Pressed Metal		

ROOM NAME APPARATUS ROOM NO. 1

ROOM NO. B14

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Painted Concrete	Good	Drain lines from machinery jury rigged into floor drains. Line run exposed across the floor.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted Concrete	Good	
CEILING	Exposed	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEN

ROOM NO. B15

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazo	Good	Several blocks need replacing in south and west walls. Door hardware has been jury rigged. Western most toilet stall has had the water closet removed and a jury rigged shower installed.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Fair/Poor	
West	Glazed Block	Fair/Poor	
CEILING	Painted Concrete	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME ELECTRIC ROOM

ROOM NO. B16

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	A long large crack exists at the east face of the transformer vault
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted Concrete	Good	
West	Painted Concrete	Good	
CEILING	Exposed Concrete		
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME TRANSFORMER VAULT

ROOM NO. B16A

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Large crack in block wall (south) at door lintel rising diagonally.
BASE	None		
WALLS:			
North	Painted Concrete	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Fair	
West	Painted C.M.U.	Good	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Fair/Good	
DOOR FRAME(s)	Pressed Metal	Fair/Good	

ROOM NAME ENERGY GENERATOR

ROOM NO. B17

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Fair/Good	Some minor cracking in floor.
BASE	None		
WALLS:			
North	Painted Concrete	Good	
East	Painted C.M.U.	Good	
South	Painted Concrete	Good	
West	Pn'td.Conc./C.M.U.	Good	
CEILING	Exposed Concrete		
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STAGE DIMMING EQUIPMENT

ROOM NO. B18

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Painted Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted Concrete	Good	
West	Painted Concrete	Good	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME STORAGE

ROOM NO. B19

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Both frame and door are badly bent.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted Concrete	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Poor	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME ELEVATOR MACHINE ROOM

ROOM NO. B20

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Painted Concrete	Very Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted Concrete	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME CLOSET

ROOM NO. B21

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Door hardware needs to be re-placed.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair/Poor	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STORAGE

ROOM NO. B22

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Pn'td.Conc./C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME APPARATUS ROOM NO. 2

ROOM NO. B23

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Poor/Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STORAGE

ROOM NO. B24

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted Concrete	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Fair/Poor	

ROOM NAME ELECTRICAL SHOP OFFICE

ROOM NO. B24A

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete		This room has been added to since original.
BASE	None		
WALLS:			
North	Painted C.M.U.		
East	Wd.Stud/Plywood		
South	Wd.Stud/Plywood		
West	Painted C.M.U.		
CEILING	Exposed Concrete		
DOOR(s)	Wood Solid Core		
DOOR FRAME(s)	Wood		

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME SERVICE CONNECTION WITH HOTEL
ROOM NO. B25

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North			
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed Concrete	Good	
DOOR(s)	Steel Roll-Up	Good	
DOOR FRAME(s)	Steel Channel	Good	

ROOM NAME STORAGE
ROOM NO. B26

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Fair/Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted Concrete	Good	
West	Painted C.M.U	Good	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Poor/Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME VESTIBULE

ROOM NO. B26A

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Extensive graffiti on walls.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted Concrete	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME SHOP

ROOM NO. B27

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Hardware completely missing from door.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted Concrete	Good	
South	Painted Concrete	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Poor	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME SHOP

ROOM NO. B28

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted Concrete	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Fair/Poor	
DOOR FRAME(s)	Pressed Metal	Fair/Poor	

ROOM NAME SHOP

ROOM NO. B29

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good/Fair	Hardware missing on door.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good/Fair	
East	Painted Concrete	Good/Fair	
South	Painted C.M.U.	Good/Fair	
West	Painted C.M.U.	Good/Fair	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Poor	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME SHOP

ROOM NO. B30

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Fair	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good/Fair	
East	Painted C.M.U.	Good/Fair	
South	Painted C.M.U.	Good/Fair	
West	Painted C.M.U.	Good/Fair	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Poor	

ROOM NAME APPARATUS ROOM NO. 3

ROOM NO. B31

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Condensate lines discharge onto floor and into floor drains.
BASE	None		
WALLS:			
North	Painted Concrete	Good	
East	Painted Concrete	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STORAGE

ROOM NO. B32

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted Concrete	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed Concrete	Good	
DOOR(s)	Steel Roll-Up	Good	
DOOR FRAME(s)	Steel Channel	Good	

ROOM NAME TELEPHONE FRAME ROOM

ROOM NO. B33


ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Fair	Considerable amount of vinyl base missing.
BASE	Vinyl	Poor	
WALLS:			
North	Painted Concrete	Good	
East	Painted Concrete	Good	
South	Painted Concrete	Good	
West	Painted Concrete	Good	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Steel Channel	Good	

Architectural Reconnaissance Survey

Mezzanine

Kallmann, McKinnell & Wood, Architects, Inc.





MEZZANINE PLAN

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STORAGE
ROOM NO. M01

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted Concrete	Good	
West	Painted C.M.U.	Good	
CEILING	Painted Concrete	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME WOMEN'S LOCKER ROOM
ROOM NO. M02

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Some minor cracking in floor and ceiling. Door closure is missing. Door needs hardware.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted Concrete	Good	
West	Painted C.M.U.	Good	
CEILING	Painted Concrete	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME WOMEN

ROOM NO. M03

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Some toilet accessories missing. Sink hardware missing.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Painted Concrete	Good	
DOOR(s)	None		
DOOR FRAME(s)	None		

ROOM NAME CORRIDOR

ROOM NO. M04

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Fair/Good	Water fountain inoperative.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Painted Concrete	Good	
DOOR(s)	Hollow Metal	Fair/Good	
DOOR FRAME(s)	Pressed Metal		

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEN

ROOM NO. M05

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Half of the water closets and urinals do not work; a large portion of those that do leak when flushed.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Painted Concrete	Good	
DOOR(s)	None		
DOOR FRAME(s)	None		

ROOM NAME CLOSET

ROOM NO. M06

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Hardware is missing from door.
BASE	None		
WALLS:			
North	None		
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Painted Concrete	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEN'S LOCKER ROOM

ROOM NO. M07

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Fair	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Painted Concrete	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME CLOSET

ROOM NO. M08

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Door		
CEILING	Painted Concrete	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME PASSAGE

ROOM NO. M09

ITEM	MATERIAL	CONDITION	REMARKS:
------	----------	-----------	----------

FLOOR	Concrete		
-------	----------	--	--

BASE	None		
------	------	--	--

WALLS:

North	Pn'td. Conc. & Block	Good	
East	Pn'td. Conc. & Block	Good	
South	Pn'td. Conc. & Block	Good	
West	Doors		

CEILING	Pn'td. Expos. Conc.		
---------	---------------------	--	--


DOOR(s)	Hollow Metal	Good	
---------	--------------	------	--

DOOR FRAME(s)	Pressed Metal	Good	
---------------	---------------	------	--

Architectural Reconnaissance Survey

First Floor

Kallmann, McKinnell & Wood, Architects, Inc.



FIRST FLOOR PLAN

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME PRESS

ROOM NO. 101

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Carpet	Poor	Carpeting is covered with water-spots. New base required. Ceiling tile out of alignment and covered with soot from air supply.
BASE	Removed		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Perf. Metal Tile	Poor	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME STORAGE

ROOM NO. 102

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Lighting - exposed bulb.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Pn'td. Gypsum Board	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME WOMEN

ROOM NO. 103

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair	Some extensive cracking. Toilet partitions are in good condition.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME JANITOR'S CLOSET

ROOM NO. 104

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Lighting - exposed bulb.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Gypsum Board	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEN

ROOM NO. 105

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Some ceiling tile needs to be replaced. Toilet partitions are in good condition.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Good/Fair	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME OFFICE

ROOM NO. 106

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Carpet	Fair	Some waterspots on carpet. Ceiling tile out of alignment and covered with spot from air supply.
BASE	Vinyl	Fair	
WALLS:			
North	Gypsum Board	Fair	
East	Mtl. Panel Over Blk.	Fair/Good	
South	Mtl. Panel Over Blk.	Fair/Good	
West	Gypsum Board	Fair	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME OFFICE

ROOM NO. 106A

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Carpet	Fair/Poor	Some waterspots on carpet. This space has been added since original building and generally consists of poor workmanship. Cut out at south wall to allow passage of original lighting.
BASE	Vinyl	Fair/Poor	
WALLS:			
North	Glazed	Good	
East	Gyp.Bd.on Mtl.Stud	Fair/Poor	
South	Gyp.Bd.on Mtl.Stud	Fair/Poor	
West	Demount. Mtl. Part.	Fair	
CEILING	Perf. Metal Tile	Poor	
DOOR(s)	Hollow Core	Good	
DOOR FRAME(s)	Wood	Good	

ROOM NAME CORRIDOR VESTIBULE

ROOM NO. 106B

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Carpet	Fair	
BASE	Vinyl	Fair	
WALLS:			
North	Gyp.Bd.on Mtl. Stud	Fair	
East	Gypsum Board *	Fair	
South	Gypsum Board *	Fair	
West	Gypsum Board *	Fair	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

* and Demountable Metal Partition

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME CLOSET

ROOM NO. 107

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Poor	Lighting - exposed bulb.
BASE	Vinyl	Good	
WALLS:			
North	Demount. Mtl. Part.	Good	
East	Demount. Mtl. Part.	Good	
South	Demount. Mtl. Part.	Good	
West	Demount. Mtl. Part.	Good	
CEILING	Perf. Metal Tile	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME CLOSET

ROOM NO. 108

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Carpet	Good	Lighting - exposed bulb.
BASE	Vinyl	Good	
WALLS:			
North	Demount. Mtl. Part.	Good	
East	Demount. Mtl. Part.	Good	
South	Demount. Mtl. Part.	Good	
West	Demount. Mtl. Part.	Good	
CEILING	Perf. Metal Tile	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME OFFICE

ROOM NO. 109

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Carpet	Poor	Ceiling tile out of alignment. No edge strip or threshold on carpeting.
BASE	Vinyl	Good	
WALLS:			
North	Demount. Mtl. Part.	Good	
East	Demount. Mtl. Part.	Good	
South	Demount. Mtl. Part.	Good	
West	Demount. Mtl. Part.	Good	
CEILING	Perf. Metal Tile	Poor	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME OFFICE

ROOM NO. 110

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Carpet	Fair	Ceiling tile out of alignment. No edge strip or threshold on carpeting.
BASE	Vinyl	Fair	
WALLS:			
North	Glazed		
East	Demount. Mtl. Part.	Fair	
South	Demount. Mtl. Part.	Fair	
West	Demount. Mtl. Part.	Fair	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME CLOSET

ROOM NO. 111

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Carpet	Poor	Lighting - exposed bulb.
BASE	Vinyl	Good	
WALLS:			
North	Demount. Mtl. Part.	Good	
East	Demount. Mtl. Part.	Good	
South	Demount. Mtl. Part.	Good	
West	Demount. Mtl. Part.	Good	
CEILING	Perf. Metal Tile	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME CLOSET

ROOM NO. 112

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Carpet	Good	Lighting - Exposed bulb.
BASE	Vinyl	Good	
WALLS:			
North	Demount. Mtl. Part.	Good	
East	Demount. Mtl. Part.	Good	
South	Demount. Mtl. Part.	Good	
West	Demount. Mtl. Part.	Good	
CEILING	Perf. Metal Tile	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME CONFERENCE

ROOM NO. 113

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Carpet	Fair	Ceiling tile out of alignment and covered with soot from air supply. Some soiling of carpet. Telephone service wires run exposed across floor
BASE	Vinyl	Fair	
WALLS:			
North	Glazed	Good	
East	Demount. Mtl. Part.	Good	
South	Demount. Mtl. Part.	Good	
West	Demount. Mtl. Part.,	Good	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME OFFICE

ROOM NO. 114

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Carpet	Good	Ceiling tile out of alignment.
BASE	Vinyl	Good	
WALLS:			
North	Glazed	Good	
East	Demount. Mtl. Part.	Good	
South	Demount. Mtl. Part.	Good	
West	Demount. Mtl. Part.	Good	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STORAGE

ROOM NO. 115

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Fair	
East	Painted C.M.U.	Fair	
South	Painted C.M.U.	Fair	
West	Painted C.M.U.	Fair	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME CORRIDOR

ROOM NO. 116

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	West - V.A.T. East - Carpet	Good Poor	Some sections of base are missing.
BASE	Vinyl	Fair	
WALLS:			
North	Demount. Mtl. Part.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Demount. Mtl. Part.	Good	
CEILING	Perf. Metal Tile	Fair/Poor	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MANAGER

ROOM NO. 117

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Carpet	Good	Ceiling tile out of alignment and covered with soot from air supply.
BASE	Vinyl	Good	
WALLS:			
North	Glazed	Good	
East	Demount. Mtl. Part.	Good	
South	Demount. Mtl. Part.	Good	
West	Demount. Mtl. Part.	Good	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME CLOSET

ROOM NO. 118

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Good	Lighting - exposed bulb.
BASE	Vinyl	Good	
WALLS:			
North	Demount. Metal Part.	Good	
East	Demount. Metal Part.	Good	
South	Demount. Metal Part.	Good	
West	Plaster on C.M.U.	Good	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME CLOSET

ROOM NO. 119

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Carpet	Good	Lighting - exposed bulb. West wall ends 6" below ceiling.
BASE	Vinyl	Good	
WALLS:			
North	Demount. Metal Part.	Good	
East	Demount. Metal Part.	Good	
South	Demount. Metal Part.	Good	
West	Plaster on C.M.U.	Good	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME VAULT

ROOM NO. 120

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Concrete	Good	
East	Concrete	Good	
South	Concrete	Good	
West	Concrete	Good	
CEILING	Concrete	Good	
DOOR(s)	Metal Vault Door	Good	
DOOR FRAME(s)	Part of Vault Door Assembly	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME OFFICE

ROOM NO. 121

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Carpet	Fair	Some soiling of carpet.
BASE	Vinyl	Good	
WALLS:			
North	Glazed	Good	
East	Demount. Metal Part.	Good	
South	Demount. Metal Part.	Good	
West	Demount. Metal Part.	Good	
CEILING	Perf. Metal Tile		
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME CONCESSION AREA

ROOM NO. 122

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Poor	Door and frame are dented extensively.
BASE	None		
WALLS:			
North	Glzd.Blk./Pn'td CMU	Good/Fair	
East	Glzd.Blk./Pn'td CMU	Good/Fair	
South	None		
West	Glzd.Blk./Pn'td CMU	Good/Fair	
CEILING	Painted Concrete	Good	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Poor	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME VESTIBULE

ROOM NO. 123

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Extensive corrosion of frame at sill level.
BASE	Vinyl	Poor	
WALLS:			
North	Glazed	Good	
East	Demount. Metal Part.	Good	
South	Demount. Metal Part.	Good	
West	Demount. Metal Part.	Good	
CEILING	Plaster	Good	
DOOR(s)	Glazed Aluminum	Fair	
DOOR FRAME(s)	Aluminum	Poor	

ROOM NAME FIRST AID

ROOM NO. 124

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Fair/Good	
BASE	Vinyl	Fair/Good	
WALLS:			
North	Glazed	Good	
East	Demount. Mtl. Part.	Good	
South	Demount. Mtl. Part.	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME TOILET

ROOM NO. 125

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Good	Corrosion on north and south walls.
BASE	Vinyl	Fair	
WALLS:			
North	Demount. Mtl. Part.	Poor	
East	Demount. Mtl. Part.	Poor	
South	Demount. Mtl. Part.	Poor	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Fair/Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME OFFICE

ROOM NO. 126

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Good	Ceiling tile covered with soot at air supply.
BASE	Vinyl	Good	
WALLS:			
North	Demount. Mtl. Part.	Good	
East	Demount. Mtl. Part.	Good	
South	Demount. Mtl. Part.	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Fair/Poor	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME TOILET

ROOM NO. 127

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Fair	
BASE	Vinyl	Poor	
WALLS:			
North	Demount. Mtl. Part.	Poor	
East	Demount. Mtl. Part.	Poor	
South	Demount. Mtl. Part.	Poor	
West	Glazed Block	Poor	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME FIRST AID

ROOM NO. 128

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Fair/Good	
BASE	Vinyl	Fair	
WALLS:			
North	Demount. Mtl. Part.	Good	
East	Demount. Mtl. Part.	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME LOUNGE
ROOM NO. 129

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Some minor cracking of terrazzo.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	Louvered Hollow Mtl.	Fair/Good	
DOOR FRAME(s)	Pressed Metal	Fair/Good	

ROOM NAME WOMEN
ROOM NO. 130

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Poor	Extensive cracking of terrazzo. Toilet stalls are in poor condition.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	None		
DOOR FRAME(s)	None		

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEN

ROOM NO. 131

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Poor	Extensive cracking of terrazzo. Ceiling tile is out of alignment. Toilet stalls are in poor condition.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Poor	
DOOR(s)	None		
DOOR FRAME(s)	None		

ROOM NAME JANITOR'S CLOSET

ROOM NO. 132

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair	Some minor cracking of terrazzo.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Plaster	Poor	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME VESTIBULE

ROOM NO. 133

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Poor	Extensive cracking of terrazzo. Ceiling tile is out of alignment.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Poor	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME OFFICE

ROOM NO. 134

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Carpet	Good	Ceiling tile is out of alignment.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Acoustic Tile	Good/Fair	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME OFFICE

ROOM NO. 135

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Carpet	Good	Some ceiling tile is chipped. This room is used by Hub Catering.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Acoustic Tile	Fair	
DOOR(s)	H.M. w/Wire Glass	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME TELEPHONE ALCOVE

ROOM NO. 136

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Some minor cracking at cased opening. Expansion joint at floor and wall needs repair.
BASE	Terrazzo	Good	
WALLS:			
North	Vinyl Wallpaper	Fair/Poor	
East	Vinyl Wallpaper	Fair/Poor	
South	Vinyl Wallpaper	Fair/Poor	
West	Vinyl Wallpaper	Fair/Poor	
CEILING	Acoustic Tile	Poor	
DOOR(s)	None		
DOOR FRAME(s)	Cased Marble Opening	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME FOYER

ROOM NO. 137

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Doors and frames at north wall are in need of replacement. Marble walls have some minor cracking. Some cracking of terrazzo in front of escalators. Doors at Dalton Street are in poor condition.
BASE	Terrazzo	Good	
WALLS:			
North	Glazed Doors	Fair/Poor	
East	Marble	Good	
South	Marble	Good	
West	Marble	Good	
CEILING	Acoustic Tile	Fair/Poor	
DOOR(s)	Glazed/Aluminum	Fair/Poor	
DOOR FRAME(s)	Aluminum	Fair/Poor	

ROOM NAME VESTIBULE

ROOM NO. 138

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Some minor cracking of plaster ceiling. Recessed floor mats are in fair condition.
BASE	Terrazzo	Good	
WALLS:			
North	Glazed Doors	Fair	
East	Marble	Good	
South	Glazed Doors	Fair/Poor	
West	Marble	Good	
CEILING	Plaster	Fair	
DOOR(s)	Glazed/Aluminum	Fair	
DOOR FRAME(s)	Aluminum	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME CLOSET
ROOM NO. 139

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Fair	
BASE	Vinyl	Fair	
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Acoustic Tile	Poor	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME OFFICE
ROOM NO. 140

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Poor	
BASE	Vinyl	Poor	
WALLS:			
North	Fabric Wallcovering	Fair	
East	Wood Paneling	Fair	
South	Fabric Wallcovering	Fair	
West	Fabric Wallcovering	Fair	
CEILING	Acoustic Tile	Poor	
DOOR(s)	Hollow Core	Poor	
DOOR FRAME(s)	Wood	Poor	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STORAGE VESTIBULE

ROOM NO. 140A

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Fair/Good	The west wall has been added since original building.
BASE	Vinyl	Fair/Poor	
WALLS:			
North	Fabric Wallcovering	Fair	
East	Fabric Wallcovering	Fair	
South	Fabric Wallcovering	Fair	
West	Wood Paneling	Fair	
CEILING	Acoustic Tile	Fair/Poor	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME TICKETS
ROOM NO. 141

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Fair	Ceiling tile is covered with soot from air supply.
BASE	Vinyl	Fair	
WALLS:			
North	Painted C.M.U.	Fair	
East	Painted C.M.U.	Fair	
South	Painted C.M.U.	Fair	
West	Painted C.M.U.	Fair	
CEILING	Acoustic Tile	Poor	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME TELEPHONE ALCOVE
ROOM NO. 142

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Some minor cracking in terrazzo and marble.
BASE	Terrazzo	Good	
WALLS:			
North	Vinyl Wallcovering	Fair/Poor	
East	Vinyl Wallcovering	Fair/Poor	
South	Vinyl Wallcovering	Fair/Poor	
West	Vinyl Wallcovering	Fair/Poor	
CEILING	Acoustic Tile	Fair	
DOOR(s)	None	Fair	
DOOR FRAME(s)	Cased Marble		

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME OFFICE

ROOM NO. 143

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Good/Fair	
BASE	V.A.T.	Good	
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Acoustic Tile	Poor	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME STORAGE

ROOM NO. 144

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	C.M.U.	Good	
East	C.M.U.	Good	
South	C.M.U.	Good	
West	C.M.U.	Good	
CEILING	None		
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STORAGE

ROOM NO. 145

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Acoustic Tile	Fair	
DOOR(s)	Accordion Vinyl	Poor	
DOOR FRAME(s)	Pressed Metal	Poor	

ROOM NAME JANITOR'S CLOSET

ROOM NO. 146

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Some hardware missing from door.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Plaster	Fair	
DOOR(s)	Hollow Metal	Fair/Poor	
DOOR FRAME(s)	Pressed Metal	Fair/Poor	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME ALCOVE

ROOM NO. 146A

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Hardware missing from door. Wallcovering is ripped and peeling. Door has extensive scratches and needs painting. Some minor cracking of terrazzo.
BASE	Terrazzo	Poor	
WALLS:			
North	Vinyl Wallcovering	Poor	
East	Vinyl Wallcovering	Poor	
South	Vinyl Wallcovering	Poor	
West	Vinyl Wallcovering	Poor	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Poor	

ROOM NAME ALCOVE

ROOM NO. 147

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Some minor cracking of terrazzo. Door closure has been jury-rigged to door.
BASE	Terrazzo	Good	
WALLS:			
North	Vinyl Wallcovering	Fair/Poor	
East	Vinyl Wallcovering	Fair/Poor	
South	Vinyl Wallcovering	Fair/Poor	
West	Vinyl Wallcovering	Fair/Poor	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Poor	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME LOUNGE

ROOM NO. 148

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair/Good	Ceiling tile is out of alignment. One major crack in terrazzo. Graffiti on wall.
BASE	Terrazzo	Good	
WALLS:			
North	Vinyl Wallcovering	Fair/Poor	
East	Vinyl Wallcovering	Fair/Poor	
South	Vinyl Wallcovering	Fair/Poor	
West	Vinyl Wallcovering	Fair/Poor	
CEILING	Perf. Metal Tile	Fair/Poor	
DOOR(s)	None		
DOOR FRAME(s)	None		

ROOM NAME CLOSET

ROOM NO. 149

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Plaster	Good/Fair	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME CLOSET

ROOM NO. 150

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Plaster	Fair	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME MEN

ROOM NO. 151

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Toilet stalls are in poor condition. Some block needs to be replaced. Compartment doors missing. Partition brackets pulling out from wall. Some minor cracking of terrazzo.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Poor	
DOOR(s)	None		
DOOR FRAME(s)	None		

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME WOMEN

ROOM NO. 152

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair	A lot of minor cracking of terrazzo. Some minor graffiti on toilet partitions.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good/Fair	
South	Glazed Block	Good	
West	Glazed Block	Good/Fair	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	None		
DOOR FRAME(s)	None		

ROOM NAME WOMEN

ROOM NO. 153

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Poor	Extensive cracking of terrazzo. Some minor scratching of toilet partitions.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Fair/Poor	
DOOR(s)	None		
DOOR FRAME(s)	None		

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME AUDITORIUM

ROOM NO. 154

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	All walls acoustically treated with metal perforated panels. Wood handrails on walls have some severe damage. Ceiling damage at Dalton Street vehicular entrance.
BASE	Vinyl	Fair/Poor	
WALLS:			
North	Plaster on Block		
East	Plaster on Block	Fair	
South	Plaster on Block	Fair	
West	Pn'td. Gypsum Bd.	Fair	
CEILING	Acous. Tile/Plaster	Fair - Tile; Good - Plaster.	
DOOR(s)	Hollow Metal		
DOOR FRAME(s)	Pressed Metal		

ROOM NAME STORAGE

ROOM NO. 155

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Fair/Good	Some cracking at head of west wall.
BASE	V.A.T.	Poor	
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Fair	
CEILING	Plaster	Good/Fair	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME TOILET

ROOM NO. 155A

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Block missing in west wall; open to stair well. Door is missing hardware and has many dents.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Poor	
CEILING	Plaster	Good	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STAGE

ROOM NO. 156

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Wood	Fair/Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	None		
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME PASSAGE

ROOM NO. 157

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Fair	Some minor cracking of concrete. Graffiti on east wall and corner is badly chipped.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Fair/Good	
South	None		
West	Painted C.M.U.	Good	
CEILING	Plaster	Fair/Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME DRESSING ROOM (THIS SPACE DOES NOT EXIST.)

ROOM NO. 158

ITEM	MATERIAL	CONDITION	REMARKS:
------	----------	-----------	----------

FLOOR

BASE

WALLS:

North
East
South
West

CEILING

DOOR(s)

DOOR FRAME(s)

ROOM NAME

ROOM NO. 159 (THIS SPACE DOES NOT EXIST.)

ITEM	MATERIAL	CONDITION	REMARKS:
------	----------	-----------	----------

FLOOR

BASE

WALLS:

North
East
South
West

CEILING

DOOR(s)

DOOR FRAME(s)

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME WOMEN

ROOM NO. 160

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair	Some minor cracking of terrazzo. Ceiling tile is out of alignment. Toilet partitions are in fair/ good condition.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Fair/Poor	
DOOR(s)	None		
DOOR FRAME(s)	None		

ROOM NAME LOUNGE

ROOM NO. 161

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair	Some minor cracking of terrazzo. South wall has several chipped blocks. Ceiling tile is out of alignment.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Fair	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Fair/Poor	
DOOR(s)	Hollow Metal		
DOOR FRAME(s)	Pressed Metal		

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME JANITOR'S CLOSET

ROOM NO. 162

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair	Some minor cracking of terrazzo.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Poor	
CEILING	Plaster	Fair	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME ALCOVE

ROOM NO. 163

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair	Some minor cracking of terrazzo.
BASE	None		Hardware missing from door. Ceiling tile is out of alignment.
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Fair/Poor	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEN

ROOM NO. 164

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair	Some minor cracking of terrazzo. Ceiling tile is out of alignment. Toilet partitions are in poor to fair condition.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Fair/Poor	
DOOR(s)	None		
DOOR FRAME(s)	None		

ROOM NAME DRESSING

ROOM NO. 165

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Good	A lot of V.A.T. base is either missing or pulling away from the wall.
BASE	V.A.T.	Poor	
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Plaster	Fair/Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME DRESSING

ROOM NO. 165A

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Good	Some V.A.T. base missing. Minor cracks in north and east walls.
BASE	V.A.T.	Fair	
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Plaster	Fair	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Poor	

ROOM NAME PASSAGE

ROOM NO. 166

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Some minor cracking in concrete.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	None		
CEILING	Plaster	Good	
DOOR(s)	None		
DOOR FRAME(s)	None		

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEN

ROOM NO. 167

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Plaster	Good/Fair	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME WOMEN

ROOM NO. 168

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Plaster	Fair	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEN'S SHOWER

ROOM NO. 169

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR			Precast base (terrazzo) marble enclosure. All in good condition.
BASE			
WALLS:			
	North		
	East		
	South		
	West		
CEILING			
DOOR(s)			
DOOR FRAME(s)			

ROOM NAME WOMEN'S SHOWER

ROOM NO. 170

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR			Precast base (terrazzo) marble enclosure. All in good condition.
BASE			
WALLS:			
	North		
	East		
	South		
	West		
CEILING			
DOOR(s)			
DOOR FRAME(s)			

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME JANITOR'S CLOSET

ROOM NO. 171

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair	Minor cracking in terrazzo.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Plaster	Fair	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME ELECTRIC CLOSET

ROOM NO. 172

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Holes in floor and wall remain from pipe removal.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Painted Concrete		
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Good/Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME ELECTRIC CLOSET

ROOM NO. 173

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Painted Concrete	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME SERVING AREA

ROOM NO. 174

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good/Fair	
BASE	None		
WALLS:			
North	Painted C.M.U.	Fair/Good	
East	Painted C.M.U.	Fair/Good	
South	Painted C.M.U.	Fair/Good	
West	Painted C.M.U.	Fair/Good	
CEILING	Painted Exposed	Good	
DOOR(s)	Hollow Metal	Fair/Good	
DOOR FRAME(s)	Pressed Metal	Fair/Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME KITCHEN (?)

ROOM NO. 175

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	None		
DOOR(s)	Hollow Metal	Fair/Good	
DOOR FRAME(s)	Pressed Metal	Fair/Good	

ROOM NAME COAT ROOM

ROOM NO. 176

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Good	East end of room requires extensive repairs; this area currently used for storage. Some ceiling tiles are missing.
BASE	Vinyl	Fair/Poor	
WALLS:			
North	Pn'td Plas.on Blk.	Fair/Poor	
East	Pn'td Plas.on Blk.	Fair/Poor	
South	Pn'td Plas.on Blk.	Fair/Poor	
West	Pn'td Plas.on Blk.	Fair/Poor	
CEILING	Acoustic Tile	Fair/Poor	
DOOR(s)	Hollow Metal	Fair/Poor	
DOOR FRAME(s)	Pressed Metal	Fair/Poor	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME TELEPHONE CLOSET

ROOM NO. 177

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	None		
DOOR(s)	Hollow Metal	Fair/Good	
DOOR FRAME(s)	Pressed Metal	Fair/Good	

ROOM NAME EXHIBITION AREA

ROOM NO. 178

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good/Fair	Minor cracking of concrete.
BASE	None		
WALLS:			
North	Painted C.M.U.	Fair/Good	
East	Painted C.M.U.	Fair/Good	
South	Painted C.M.U.	Fair/Good	
West	Painted C.M.U.	Fair/Good	
CEILING	Painted Exposed	Good	
DOOR(s)	Hollow Metal	Fair/Good	
DOOR FRAME(s)	Pressed Metal	Fair/Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME CONCESSION AREA

ROOM NO. 179

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Fair	Some chipping of tiles. Some denting and scratching of doors and frames
BASE	None		
WALLS:			
North	Glz. Blk./Pt. CMU	Good	
East			
South			
West			
CEILING	Painted Exposed	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME STAGE ANTE ROOM

ROOM NO. 179A

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good/Fair	Minor cracking of concrete.
BASE	None		
WALLS:			
North	Painted C.M.U.	Fair/Good	
East	Painted C.M.U.	Fair/Good	
South	Painted C.M.U.	Fair/Good	
West	Painted C.M.U.	Fair/Good	
CEILING	Painted Exposed	Good	
DOOR(s)	Hollow Metal	Fair/Good	
DOOR FRAME(s)	Pressed Metal	Fair/Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STORAGE

ROOM NO. 180

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	None		
DOOR(s)	Hollow Metal	Fair/Good	
DOOR FRAME(s)	Pressed Metal	Fair/Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME FOYER

ROOM NO. 181

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair	
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Gl.Alum.Drs./Trans.	Fair/Good	
West	Glazed Block	Good	
CEILING	Plaster	Good	
DOOR(s)	Glazed Aluminum	Fair	
DOOR FRAME(s)	Aluminum	Fair	

ROOM NAME TICKETS

ROOM NO. 182

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Poor	
BASE	V.A.T.	Poor	
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Plaster	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Poor	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEETING ROOM

ROOM NO. 183

ITEM	MATERIAL	CONDITION	REMARKS:
------	----------	-----------	----------

FLOOR	Concrete	Good/Fair	
-------	----------	-----------	--

BASE	None		
------	------	--	--

WALLS:

North	Folding Part.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.*	Good	
West	Folding Part.	Good	

CEILING	Painted Exposed	Good	
---------	-----------------	------	--

DOOR(s)	NOTE: Doors and frames are an integral part of		
DOOR FRAME(s)	the folding partitions.		

ROOM NAME MEETING ROOM

ROOM NO. 184

ITEM	MATERIAL	CONDITION	REMARKS:
------	----------	-----------	----------

FLOOR	Concrete	Good/Fair	
-------	----------	-----------	--

BASE	None		
------	------	--	--

WALLS:

North	Folding Part.	Good	
East	Painted C.M.U.	Good	
South	Folding Part.	Good	
West	Folding Part.	Good	

CEILING	Painted Exposed	Good	
---------	-----------------	------	--

DOOR(s)	NOTE: Doors and frames are an integral part of		
DOOR FRAME(s)	the folding partitions.		

* and folding part.

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEETING ROOM

ROOM NO. 185

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good/Fair	
BASE	None		
WALLS:			
North	Painted C.M.U.*	Good	
East	Painted C.M.U.	Fair/Good	
South	Folding Part.	Good	
West	Folding Part.	Good	
CEILING	Painted Exposed	Good	
DOOR(s)	NOTE: Doors and frames are an integral part of the folding partitions.		
DOOR FRAME(s)			

ROOM NAME TICKETS

ROOM NO. 186

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Good	Hardware missing from door.
BASE	V.A.T.	Good	
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Plaster	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEETING ROOM

ROOM NO. 187

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good/Fair	
BASE	None		
WALLS:			
North	Folding Part.	Good	
East	Painted C.M.U.	Fair/Good	
South	Painted C.M.U.*	Good	
West	Folding Part.	Fair/Good	
CEILING	Painted Exposed	Good	
DOOR(s)	NOTE: Doors and frames are an integral part of the folding partitions.		
DOOR FRAME(s)			

ROOM NAME MEETING ROOM

ROOM NO. 188

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good/Fair	
BASE	None		
WALLS:			
North	Folding Part.	Good	
East	Painted C.M.U.	Fair/Good	
South	Folding Part.	Good	
West	Folding Part.	Good	
CEILING	Painted Exposed	Good	
DOOR(s)	NOTE: Doors and frames are an integral part of the folding partitions.		
DOOR FRAME(s)			

* and Folding Part.

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEETING ROOM

ROOM NO. 189

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good/Fair	
BASE	None		
WALLS:			
North	Painted C.M.U.	Fair/Good	
East	Painted C.M.U.	Fair/Good	
South	Folding Part.	Good	
West	Folding Part.	Good	
CEILING	Painted Exposed	Good	
DOOR(s)	NOTE: Doors and frames are an integral part of the folding partitions.		
DOOR FRAME(s)			

ROOM NAME PASSAGE

ROOM NO. 190

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Good/Fair	Considerable marring of door and partitions.
BASE	Vinyl	Good/Fair	
WALLS:			
North	Demount. Metal Part.	Fair	
East	Demount. Metal Part.	Fair	
South	Painted C.M.U.	Good	
West	Demount. Metal Part.	Fair	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STORAGE

ROOM NO. 191

ITEM	MATERIAL	CONDITION	REMARKS:
------	----------	-----------	----------

FLOOR	Concrete	Good	
-------	----------	------	--

BASE	None		
------	------	--	--

WALLS:

North	Painted C.M.U.	Good	
East	Painted Concrete	Good	
South	Painted Concrete	Good	
West	Painted C.M.U.	Good	

CEILING	Painted Concrete	Good	
---------	------------------	------	--

DOOR(s)	Hollow Metal	Good	
---------	--------------	------	--

DOOR FRAME(s)	Pressed Metal	Good	
---------------	---------------	------	--

ROOM NAME STORAGE

ROOM NO. 192

ITEM	MATERIAL	CONDITION	REMARKS:
------	----------	-----------	----------

FLOOR	Concrete	Good	
-------	----------	------	--

BASE	None		
------	------	--	--

WALLS:

North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted Concrete	Good	
West	Painted Concrete	Good	

CEILING	Painted Concrete	Good	
---------	------------------	------	--


DOOR(s)	Hollow Metal	Good	
---------	--------------	------	--

DOOR FRAME(s)	Pressed Metal	Good	
---------------	---------------	------	--

Architectural Reconnaissance Survey

Second Floor

Kallmann, McKinnell & Wood, Architects, Inc.



SECOND FLOOR PLAN

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME EXHIBITION AREA

ROOM NO. 201

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good/Fair	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good/Fair	
East	Painted C.M.U.	Good/Fair	
South	Painted C.M.U.	Good/Fair	
West	Painted C.M.U.	Good/Fair	
CEILING	Painted Exposed	Good/Fair	
DOOR(s)	Hollow Metal	Fair/Poor	
DOOR FRAME(s)	Pressed Metal	Fair/Poor	

ROOM NAME CONCESSION AREA

ROOM NO. 202

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Fair	
BASE	None		
WALLS:			
North	Glazed Block below, Painted C.M.U. above.*		
East	Glazed Block below, Painted C.M.U. above.*		
South	None		
West	Glazed Block below, Painted C.M.U. above.*		
CEILING	Painted Exposed	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

* Condition - Good.

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STORAGE

ROOM NO. 203

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Fair	
East	Painted C.M.U.	Fair	
South	Painted C.M.U.	Fair	
West	Painted C.M.U.	Fair	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME SWITCHBOARD EQUIPMENT

ROOM NO. 204

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Poor	
BASE	Vinyl	Fair	
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME WOMEN

ROOM NO. 205

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair/Good	Minor cracking. Extensive cracking of block in northwest corner. One toilet partition door missing.
BASE	None		
WALLS:			
North	Glazed Block	Fair	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Good	
DOOR(s)	None		
DOOR FRAME(s)	None		

ROOM NAME LOUNGE

ROOM NO. 206

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Minor cracking. Block cracking and peeling off in northwest corner. Ceiling tiles out of alignment. Exterior door dented and scratched.
BASE	None		
WALLS:			
North	Glazed Block	Fair	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tiles	Fair	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Poor	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME VESTIBULE

ROOM NO. 207

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Some door hardware missing.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Metal Perf. Tile	Fair/Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Poor	

ROOM NAME JANITOR'S CLOSET

ROOM NO. 208

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Plaster	Fair/Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEN

ROOM NO. 209

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair	Some cracking in floor. Toilet partitions in poor condition. Ceiling over stalls covered with graffitti.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	None		
DOOR FRAME(s)	None		

ROOM NAME MEETING ROOM

ROOM NO. 210

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Good	Base pulled away from walls in places. C.M.U. cracked in northwest corner. Ceiling poorly hung with chipped and mis-matched tiles. Doors chipped, scratched and marred.
BASE	Vinyl	Poor/Fair	
WALLS:			
North	Painted C.M.U.	Fair	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Acoustic Tile	Poor/Fair	
DOOR(s)	Hollow Metal	Fair/Poor	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME PASSAGE

ROOM NO. 211

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Quarry Tile	Good	Ceiling poorly hung with mis-matched tiles.
BASE	Quarry Tile	Good	
WALLS:			
North	Glazed Block w/Vinyl	Wallcovering in Reveals*	
East	Glazed Block w/Vinyl	Wallcovering in Reveals*	
South	Glazed Block w/Vinyl	Wallcovering in Reveals*	
West	Glazed Block w/Vinyl	Wallcovering in Reveals*	
CEILING	Acoustic Tile	Fair/Poor	
DOOR(s)	H.M. w/Vision Panels	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME CLOSET

ROOM NO. 212

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

* Good Condition

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEETING ROOM

ROOM NO. 213

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Good	Extensive cracking of C.M.U. in northeast corner. Ceiling tiles poorly hung, mismatched and water spotted. Electric outlet pulled from wall, exposing wires.
BASE	Vinyl	Fair	
WALLS:			
North	Painted C.M.U.	Fair	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Fair	
CEILING	Acoustic Tile	Poor	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME MEETING ROOM

ROOM NO. 214

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Very Poor	Floor missing numerous tiles. Base missing in places, warped. Acoustic panels of perforated, corrugated metal panels on all walls. Stage-like canopy hung from west wall.
BASE	V.A.T.	Poor	
WALLS:			
North	Painted C.M.U.	Fair	
East	Painted C.M.U.	Fair	
South	Painted C.M.U.	Fair	
West	Painted C.M.U.	Fair	
CEILING	Pn'td Exposed Conc.	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEETING ROOM

ROOM NO. 215

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Fair	Cracking in block on north wall.
BASE	Vinyl	Poor	
WALLS:			
North	Painted C.M.U.	Poor	
East	Painted C.M.U.	Poor	
South	Painted C.M.U.	Poor	
West	Painted C.M.U.	Poor	
CEILING	Acoustic Tile	Very Poor	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME STAIR LOBBY

ROOM NO. 216

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Quarry Tile	Good	
BASE	Quarry Tile	Good	
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Vinyl Wallcovering	Fair	
CEILING	Acoustic Tile	Fair/Poor	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME FOYER

ROOM NO. 217

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Quarry Tile	Fair	Flooring has a number of large chips near east end. Some chipping of marble column enclosures.
BASE	Quarry Tile	Fair	
WALLS:			
North	*	Poor	
East	*	Poor	
South	Marble Cladding	Fair	
West	*	Poor	
CEILING	Acoustic Tile	Poor	
DOOR(s)	H.M. w/Vision Panel	Poor	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME STORAGE

ROOM NO. 218

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Painted Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Painted Concrete	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

* Two types of vinyl wallcovering.

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEETING ROOM

ROOM NO. 219

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Fair	
BASE	Vinyl	Fair	
WALLS:			
North	Painted C.M.U.	Good	
East	Plaster on Masonry	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Acoustical Tile	Poor	
DOOR(s)	Hollow Metal	Poor/Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME STAIR LOBBY

ROOM NO. 220

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Quarry Tile	Good	Block walls have vinyl wall-covering trim in reveals.
BASE	Quarry Tile	Good	
WALLS:			
North	Glazed Block	Good	
East	Vinyl Wallcovering	Poor	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Acoustical Tile	Poor	
DOOR(s)	H.M. w/Vision Panel	Poor	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME TELEPHONE ALCOVE

ROOM NO. 221

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Quarry Tile	Good	4 metal telephone booths on north wall.
BASE	Quarry Tile	Good	
WALLS:			
North	Vinyl Wallcovering	Poor	
East	Vinyl Wallcovering	Poor	
South	Vinyl Wallcovering	Poor	
West	Vinyl Wallcovering	Poor	
CEILING	Acoustical Tile	Fair	
DOOR(s)	None		
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME JANITOR'S CLOSET

ROOM NO. 222

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair	
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Plaster	Fair	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME ALCOVE

ROOM NO. 222A

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Quarry Tile	Good	
BASE	Quarry Tile	Good	
WALLS:			
North	Vinyl Wallcovering	Fair	
East	Vinyl Wallcovering	Fair	
South	Vinyl Wallcovering	Fair	
West	Vinyl Wallcovering	Fair	
CEILING	Plaster	Good	
DOOR(s)			
DOOR FRAME(s)	Marble Cased Opng.	Good	

ROOM NAME MEN

ROOM NO. 223

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair	Flooring has begun to deteriorate beneath urinals.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Poor/Fair	
DOOR(s)	None		
DOOR FRAME(s)	Hollow Metal Framed Opening		

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME LOUNGE

ROOM NO. 224

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Quarry Tile	Good	
BASE	Quarry Tile	Good	
WALLS:			
North	Vinyl Wallcovering	Fair	
East	Vinyl Wallcovering	Fair	
South	Vinyl Wallcovering	Fair	
West	Vinyl Wallcovering	Fair	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME CONCESSION AREA

ROOM NO. 225

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Quarry Tile	Fair/Good	Some discoloration of glazed block in southwest corner. Marble cased opening badly chipped at west corner.
BASE	Quarry Tile	Fair/Good	
WALLS:			
North	None		
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Acoustic Tile	Very Poor	
DOOR(s)	H.M. w/Louvers	Very Poor	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STORAGE

ROOM NO. 226

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Large horizontal crack in south wall ceiling is under side of bleachers. Absence of shelving or other storage system results in under utilization of space (typical).
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Fair	
West	Painted C.M.U.	Good	
CEILING	Pn'td. Expos. Conc.	Good	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME BALCONY

ROOM NO. 227

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Fair	Minor cracking in floor. Base frequently missing. Perforated metal acoustic panels on all walls in fair/good condition. Upholstery on all seats worn. Some seat covers have been replaced with mismatched fabric. Rows and aisles poorly identified with handmade signs.
BASE	Vinyl	Very Poor	
WALLS:			
North	Vinyl Wallcovering	Poor	
East	Vinyl Wallcovering	Fair	
South	Mtl.Acous.Wall.Trtmt.	Good	
West	Vinyl Wallcovering	Fair	
CEILING	Alcove: Acous. Tile	Good	
	Main Audit.: Pn'td.		
DOOR(s)	Exposed w/Acous.Panels	Good	
	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME LOUNGE

ROOM NO. 228

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Quarry Tile	Good	
BASE	Quarry Tile	Good	
WALLS:			
North	Vinyl Wallcovering	Poor	
East	Vinyl Wallcovering	Poor	
South	Vinyl Wallcovering	Poor	
West	Vinyl Wallcovering	Poor	
CEILING	Perf. Metal Tiles	Poor	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME ALCOVE

ROOM NO. 229

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Quarry Tile	Good	Exposed electrical conduit running from Room 225 to Alcove.
BASE	Quarry Tile	Good	
WALLS:			
North	Vinyl Wallcovering	Fair	
East	Vinyl Wallcovering	Fair	
South	Vinyl Wallcovering	Fair	
West	Vinyl Wall Covering	Fair	
CEILING	Plaster	Good	
DOOR(s)	None		
DOOR FRAME(s)	Cased Marble Opening	Fair/Some cracking	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME JANITOR'S CLOSET

ROOM NO. 230

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair	Some water spotting on ceiling.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Plaster	Fair	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME WOMEN

ROOM NO. 231

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Toilet partitions in good condition.
BASE	None		
WALLS:			
North	Glazed Block	Good/Fair	
East	Glazed Block	Good/Fair	
South	Glazed Block	Good/Fair	
West	Glazed Block	Good/Fair	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	None		
DOOR FRAME(s)	Hollow Metal Cased Opening		

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEETING ROOM

ROOM NO. 232

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Good	
BASE	Vinyl	Fair/Good	
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Fair	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Pn'td.Expos.Conc.	Good	
DOOR(s)	H.M. w/Vision Panel	Fair	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME MEETING ROOM

ROOM NO. 233

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Good	Large (4' x 4') fluorescent lights hung in low (9'-0") space.
BASE	Vinyl	Fair	
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Pn'td.Expos.Conc.	Good	
DOOR(s)	H.M. w/Vision Panel	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEETING ROOM

ROOM NO. 234

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Carpet, V.A.T.	Fair	Carpet fastened to V.A.T. with masking tape. 4' x 4' fluorescent lights suspended from 9'-0" ceiling.
BASE	Vinyl	Fair	
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Pn'td.Expos.Conc.	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME MECHANICAL APPARATUS ROOM

ROOM NO. 235

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Painted Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEETING ROOM

ROOM NO. 236

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Carpet, V.A.T.	Poor	Carpet is fastened to mismatched V.A.T. with masking tape. Sink on north wall. Electrical service cord running into room from corridor.
BASE			
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Acoustical Tile	Poor	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME PASSAGE

ROOM NO. 236A

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Fair/Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Plaster	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME JANITOR'S CLOSET

ROOM NO. 236B

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair	
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Plaster	Fair/Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME MEETING ROOM

ROOM NO. 237

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Carpet, V.A.T.	Poor	Carpeting is fastened to mismatched V.A.T. with masking tape. Sink on south wall.
BASE	Vinyl	Good	
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Acoustic Tile	Poor	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME CLOSET

ROOM NO. 237A

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Painted Concrete	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	good	

ROOM NAME ELECTRIC CLOSET

ROOM NO. 238

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Painted Concrete	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME ELECTRICAL CLOSET

ROOM NO. 239

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed	Good	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME MEN

ROOM NO. 240

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Toilet partitions in fair condition. Two stalls missing doors.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Poor	
DOOR(s)	None		
DOOR FRAME(s)	None		

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME VESTIBULE

ROOM NO. 241

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair	
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	Hollow Metal	Fair/Poor	
DOOR FRAME(s)	Pressed Metal	Fair/Poor	

ROOM NAME Women

ROOM NO. 243

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair	Toilet partitions in good/fair condition.
BASE	None		One door needs to be replaced.
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Fair	
DOOR(s)	None		
DOOR FRAME(s)	None		

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME LOUNGE

ROOM NO. 244

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair	Door missing hardware.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Fair	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Fair/Poor	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME CONCESSION AREA

ROOM NO. 245

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Good	
BASE	None		
WALLS:			
North	None		
East	*	Good	
South	*	Good	
West	*	Good	
CEILING	Pn'td.Expos.Conc.	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

* Glazed Block Below, Painted C.M.U. Above.

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STORAGE

ROOM NO. 246

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Fair	
East	Painted C.M.U.	Fair	
South	Painted C.M.U.	Fair	
West	Painted C.M.U.	Fair	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME MEETING ROOM (MODULAR)

ROOM NO. 247

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good/Fair	
BASE	None		
WALLS:			
North	Folding Partition	Good/Fair	
East	Painted C.M.U.	Good/Fair	
South	Painted C.M.U.	Good/Fair	
West	Folding Partition	Good/Fair	
CEILING	Painted Exposed	Good	
DOOR(s)	NOTE: Doors and frames are an integral part of the folding partitions.		
DOOR FRAME(s)			

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEETING ROOM

ROOM NO. 248

ITEM	MATERIAL	CONDITION	REMARKS:
------	----------	-----------	----------

FLOOR	Concrete	Good/Fair	
-------	----------	-----------	--

BASE	None		
------	------	--	--

WALLS:

North	Folding Partition	Good/Fair	
East	Painted C.M.U.	Good/Fair	
South	Folding Partition	Good/Fair	
West	Folding Partition	Good/Fair	

CEILING	Painted Exposed	Good	
---------	-----------------	------	--

DOOR(s) NOTE: Doors and frames
are an integral part of
DOOR FRAME(s) the folding partitions.

ROOM NAME MEETING ROOM

ROOM NO. 249

ITEM	MATERIAL	CONDITION	REMARKS:
------	----------	-----------	----------

FLOOR	Concrete	Good/Fair	
-------	----------	-----------	--

BASE	None		
------	------	--	--

WALLS:

North	Folding Partition	Good/Fair	
East	Painted C.M.U.	Good/Fair	
South	Folding Partition	Good/Fair	
West	Folding Partition	Good/Fair	

CEILING	Painted Exposed	Good	
---------	-----------------	------	--

DOOR(s) NOTE: Doors and frames
are an integral part of
DOOR FRAME(s) the folding partitions.

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEETING ROOM

ROOM NO. 250

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good/Fair	
BASE	None		
WALLS:			
North	Folding Partition	Good/Fair	
East	Painted C.M.U.	Good/Fair	
South	Folding Partition	Good/Fair	
West	Folding Partition	Good/Fair	
CEILING	Painted Exposed	Good	
DOOR(s)	NOTE: Doors and frames are an integral part of the folding partitions.		
DOOR FRAME(s)			

ROOM NAME MEETING ROOM

ROOM NO. 251

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good/Fair	
BASE	None		
WALLS:			
North	Painted D.M.U.	Good/Fair	
East	Painted C.M.U.	Good/Fair	
South	Folding Partition	Fair	
West	Folding Partition	Fair	
CEILING	Painted Exposed	Good	
DOOR(s)	NOTE: Doors and frames are an integral part of the folding partitions.		
DOOR FRAME(s)			

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME PASSAGE

ROOM NO. 253

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Quarry Tile	Good	
BASE	Quarry Tile	Good	
WALLS:			
North	*	Fair	
East	**	Fair	
South	*	Fair	
West	**	Fair	
CEILING	Acoustic Tile	Poor	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Poor	
* Glazed Block with Vinyl Strips in Reveals			
** Hollow Metal Doors and Transom			

ROOM NAME STORAGE

ROOM NO. 254

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Plaster	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEN'S SHOWERS

ROOM NO. 255

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Three marble shower/dressing compartments in good condition.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	None		
CEILING	Plaster	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME JANITOR'S CLOSET

ROOM NO. 256

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Plaster	Good/Fair	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME VESTIBULE

ROOM NO. 257

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perforated Tile	Poor	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME MEN

ROOM NO. 258

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perforated Tile	Fair	
DOOR(s)	None		
DOOR FRAME(s)	None		

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEN'S SHOWERS

ROOM NO. 259

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Three marble shower/dressing compartments are in good condition.
BASE	None		
WALLS:			
North	None		
East	Glazed Block	Good	
South	Glazed Block	Good	
West	None		
CEILING	Plaster	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME VESTIBULE

ROOM NO. 260

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Metal Perf. Tile	Good	
DOOR(s)	Hollow Metal	Good/Fair	
DOOR FRAME(s)	Pressed Metal	Good/Fair	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MEN

ROOM NO. 261

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Metal toilet partitions in good condition.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Good	
DOOR(s)	None		
DOOR FRAME(s)	None		

ROOM NAME JANITOR'S CLOSET

ROOM NO. 262

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Plaster	Fair/Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME VESTIBULE

ROOM NO. 263

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Metal Perf. Tile	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME CLOSET

ROOM NO. 263A

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Plaster	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME WOMEN'S SHOWERS

ROOM NO. 264

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Four marble shower/dressing compartments in good condition.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Plaster	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME WOMEN'S LAVATORIES

ROOM NO. 265

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Metal Perf. Tile	Good	
DOOR(s)	None		
DOOR FRAME(s)	None		

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME WOMEN'S TOILETS

ROOM NO. 266

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Toilet partitions in excellent condition.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Good	
DOOR(s)	None		
DOOR FRAME(s)	None		

ROOM NAME SERVICE AREA

ROOM NO. 267

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Large two compartment service sink.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Perf. Metal Tile	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME WOMEN'S SHOWERS

ROOM NO. 268

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Four shower/dressing marble compartments in good condition.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Plaster	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

Architectural Reconnaissance Survey

Third Level

Kallmann, McKinnell & Wood, Architects, Inc.

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME ELEVATOR NO. 6 MACHINE ROOM

ROOM NO. 301

ITEM	MATERIAL	CONDITION	REMARKS:
------	----------	-----------	----------

FLOOR	Concrete	Good	
-------	----------	------	--

BASE	None		
------	------	--	--

WALLS:

North	C.M.U.	Good	
East	C.M.U.	Good	
South	C.M.U.	Good	
West	C.M.U.	Good	

CEILING	Exposed	Good	
---------	---------	------	--

DOOR(s)	Hollow Metal	Good	
---------	--------------	------	--

DOOR FRAME(s)	Pressed Metal	good	
---------------	---------------	------	--

ROOM NAME CORRIDOR

ROOM NO. 302

ITEM	MATERIAL	CONDITION	REMARKS:
------	----------	-----------	----------

FLOOR	Concrete	Good	
-------	----------	------	--

BASE	Vinyl	Good	
------	-------	------	--

WALLS:

North	Acoustic Mt'l. Panels	Good	
East	Acoustic Mt'l. Panels	Good	
South	None		
West	Acoustic Mt'l. Panels	Good	

CEILING	Plaster	Good	
---------	---------	------	--

DOOR(s)	Hollow Metal	Good	
---------	--------------	------	--

DOOR FRAME(s)	Pressed Metal	Good	
---------------	---------------	------	--

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME JANITOR'S CLOSET

ROOM NO. 303

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	C.M.U.	Good	
East	C.M.U.	Good	
South	C.M.U.	Good	
West	C.M.U.	Good	
CEILING	Plaster	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME TOILET

ROOM NO. 304

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Plaster	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME REWIND ROOM

ROOM NO. 305

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Good	
BASE	Vinyl	Good	
WALLS:			
North	Plaster	Good	
East	Plaster	Good	
South	Plaster	Good	
West	Plaster	Good	
CEILING	Acoustic Tile	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME PROJECTION ROOM

ROOM NO. 306

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	Vinyl	Good	
WALLS:			
North	C.M.U./Acoustic Tile	Good	
East	C.M.U./Acoustic Tile	Good	
South	C.M.U./Acoustic Tile	Good	
West	C.M.U./Acoustic Tile	Good	
CEILING	Acoustic Tile	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME MOTION PICTURE RECTIFIER

ROOM NO. 307

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	V.A.T.	Good	
BASE	Vinyl	Good	
WALLS:			
North	Plaster	Good	
East	Plaster	Good	
South	Plaster	Good	
West	Plaster	Good	
CEILING	Acoustic Tile	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME SOUND CONTROL ROOM

ROOM NO. 308

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	C.M.U./Acoustic Tile	Good	
East	C.M.U./Acoustic Tile	Good	
South	C.M.U./Acoustic Tile	Good	
West	C.M.U./Acoustic Tile	Good	
CEILING	Acoustic Tile	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME P. A. AMPLIFIER

ROOM NO. 309

ITEM	MATERIAL	CONDITION	REMARKS:
------	----------	-----------	----------

FLOOR	V.A.T.	Good	
-------	--------	------	--

BASE	Vinyl	Good	
------	-------	------	--

WALLS:

North	Plaster	Good	
East	Plaster	Good	
South	Plaster	Good	
West	Plaster	Good	

CEILING	Acoustic Tile	Good	
---------	---------------	------	--

DOOR(s)	Hollow Metal	Good	
---------	--------------	------	--

DOOR FRAME(s)	Pressed Metal	Good	
---------------	---------------	------	--

ROOM NAME CORRIDOR

ROOM NO. 310

ITEM	MATERIAL	CONDITION	REMARKS:
------	----------	-----------	----------

FLOOR	Concrete	Good	
-------	----------	------	--

BASE	Vinyl	Good	
------	-------	------	--

WALLS:

North	Acoustic Mt'l. Panels	Good	
East	Acoustic Mt'l. Panels	Good	
South	None		
West	Acoustic Mt'l. Panels	Good	

CEILING	Plaster	Good	
---------	---------	------	--

DOOR(s)	Hollow Metal	Good	
---------	--------------	------	--

DOOR FRAME(s)	Pressed Metal	Good	
---------------	---------------	------	--

Architectural Reconnaissance Survey

Stairs

Kallmann, McKinnell & Wood, Architects, Inc.

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STAIR NO. 1

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Walls are treated with reveals. The vinyl wallcovering in the reveals of the north and west walls needs repair. Caulking is in need of work.
BASE	Terrazzo	Good	
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	None		
West	Glazed Block	Good	
CEILING	Acoustic Tile	Poor	
DOOR(s)	None		
DOOR FRAME(s)	None		

ROOM NAME STAIR NO. 2

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Some water spotting of ceiling tile.
BASE	Terrazzo	Good	
WALLS:			
North	None		
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Acoustic Tile	Fair	
DOOR(s)	None		
DOOR FRAME(s)	None		

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STAIR NO. 3

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Some minor cracking of floor and base terrazzo.
BASE	Terrazzo	Good	
WALLS:			
North	None		
East	None		
South	Railing	Good	
West	None		
CEILING	None		
DOOR(s)	None		
DOOR FRAME(s)	None		

ROOM NAME STAIR NO. 4

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Some minor chipping of nosings.
BASE	Terrazzo	Good	
WALLS:			
North	Railing	Good	
East	None		
South	None		
West	None		
CEILING	None		
DOOR(s)	None		
DOOR FRAME(s)	None		

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STAIR NO. 5

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Some minor cracking of floor and base terrazzo.
BASE	Terrazzo	Good	
WALLS:			
North	None		
East	None		
South	Railing	Good	
West	None		
CEILING	None		
DOOR(s)	None		
DOOR FRAME(s)	None		

ROOM NAME STAIR NO. 6

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Good	Some minor cracking of floor and base terrazzo.
BASE	Terrazzo	Good	
WALLS:			
North	Railing	Good	
East	None		
South	None		
West	None		
CEILING	None		
DOOR(s)	None		
DOOR FRAME(s)	None		

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STAIR NO. 7

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Some minor cracking and water spotting of ceiling. Some corrosion at base of door frame. Stair construction is concrete filled metal pan.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Plaster	Fair	
DOOR(s)	Hollow Metal	Fair/Good	
DOOR FRAME(s)	Pressed Metal	Fair/Good	

ROOM NAME STAIR NO. 8

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Ceiling has had damage from water leakage. Some minor cracking of concrete floor. Stair construction is concrete filled metal pan.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Plaster	Poor	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STAIR NO. 9

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair/Good	Telephone booths on east wall are missing phones.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Good	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Plaster	Good	
DOOR(s)	Hollow Metal		
DOOR FRAME(s)	Pressed Metal		

ROOM NAME STAIR NO. 10

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair/Good	Some minor cracking in terrazzo. Some cracking of block in east wall. Ceiling damaged at south wall. Phone booths have had phones ripped out.
BASE	None		
WALLS:			
North	Glazed Block	Good	
East	Glazed Block	Fair	
South	Glazed Block	Good	
West	Glazed Block	Good	
CEILING	Plaster	Fair	
DOOR(s)	Hollow Metal	Fair/Good	
DOOR FRAME(s)	Pressed Metal	Fair/Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STAIR NO. 11

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Stair construction is concrete filled metal pan. Some hardware missing from doors.
BASE	None		
WALLS:			
North	Pn'td. Conc./C.M.U.	Good	
East	Pn'td. Conc./C.M.U.	Good	
South	Pn'td. Conc./C.M.U.	Good	
West	Pn'td. Conc./C.M.U.	Good	
CEILING	Painted Exposed	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME STAIR NO. 12

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Stair construction is concrete filled metal pan.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Painted Exposed	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STAIR NO. 13

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Stair construction is concrete filled metal pan. Pair of doors at Mezzanine level are in poor condition.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Painted Exposed	Good	
DOOR(s)	Hollow Metal	Poor/Fair	
DOOR FRAME(s)	Pressed Metal	good	

ROOM NAME STAIR NO. 14

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Stair construction is concrete filled metal pan. Some graffiti on ceiling. Some base material missing.
BASE	Vinyl	Fair	
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Plaster	Fair/Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STAIR NO. 15

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME STAIR NO. 16

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Ceiling paint is peeling. Stair construction is concrete filled metal pan.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Plaster	Fair	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STAIR NO. 17

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Fair/Good	Wallcovering is ripped and covered with graffiti. Wood handrail needs to be refinished. Vinyl base has been almost completely removed.
BASE	Vinyl	Poor	
WALLS:			
North	Vinyl Wallcovering	Good	
East	Vinyl Wallcovering	Poor	
South	None		
West	Vinyl Wallcovering	Poor	
CEILING	Plaster	Good	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME STAIR NO. 18

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Fair/Good	Vinyl base missing in many places.
BASE	Vinyl	Poor	
WALLS:			
North	Vinyl Wallcovering	Good	
East	Vinyl Wallcovering	Poor	
South	None		
West	Vinyl Wallcovering	Good	
CEILING	Plaster	Fair	
DOOR(s)	Hollow Metal	Fair	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STAIR NO. 19

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Fair/Good	Stair construction is concrete filled metal pan.
BASE	None		
WALLS:			
North	Painted Concrete	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Plaster	Good	
DOOR(s)	Hollow Metal	Poor/Fair	
DOOR FRAME(s)	Pressed Metal	Fair	

ROOM NAME STAIR NO. 20

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	Vinyl	Good	
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Plaster	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STAIR NO. 21

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Stair construction is concrete filled metal pan.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted Concrete	Good	
West	Painted C.M.U.	Good	
CEILING	Painted Concrete	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME STAIR NO. 22

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Stair treads have metal safety nosings.
BASE	None		
WALLS:			
North	None	Good	
East	Painted C.M.U.		
South	None		
West	None		
CEILING	None		
DOOR(s)	None		
DOOR FRAME(s)	None		

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STAIR NO. 23

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	None		
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed	Good	
DOOR(s)	Hollow Metal	Good	
DOOR FRAME(s)	Pressed Metal	Good	

ROOM NAME STAIR NO. 24

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Concrete	Good	
East	None		
South	None		
West	None		
CEILING	Exposed Concrete	Good	
DOOR(s)	None		
DOOR FRAME(s)	None		

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STAIR NO. 25

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	Unit heater at north wall is in poor condition. Doors, hardware and glazed transom are all in poor condition.
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	None		
South	Painted C.M.U.	Good	
West	Doors/Glazing	Poor	
CEILING	Painted Concrete	Good	
DOOR(s)	Hollow Metal	Poor	
DOOR FRAME(s)	Pressed Metal	Poor	

ROOM NAME STAIR NO. 26

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	None		
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Fair/Good	
DOOR FRAME(s)	Pressed Metal	Fair/Good	

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STAIR NO. 27

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	Vinyl	Good	
WALLS:			
North	None		
East	None		
South	None		
West	None		
CEILING	None		
DOOR(s)	None		
DOOR FRAME(s)	None		

ROOM NAME STAIR NO. 28

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	Vinyl	Good	
WALLS:			
North	None		
East	None		
South	None		
West	None		
CEILING	None		
DOOR(s)	None		
DOOR FRAME(s)	None		

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STAIR NO. 29

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Painted C.M.U.	Good	
East	Painted C.M.U.	Good	
South	Painted C.M.U.	Good	
West	Painted C.M.U.	Good	
CEILING	Exposed Concrete	Good	
DOOR(s)	Hollow Metal	Fair/Good	
DOOR FRAME(s)	Pressed Metal	Fair/Good	

ROOM NAME STAIR NO. 30

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR			This stair is a prefabricated spiral stair. Generally in good condition.
BASE			
WALLS:			
North			
East			
South			
West			
CEILING			
DOOR(s)			
DOOR FRAME(s)			

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STAIR NO. 32

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Terrazzo	Fair	Railing is in poor condition. Terrazzo is chipped and cracked.
BASE	None		
WALLS:			
North	None		
East	Glazed Block	Good	
South	Glazed Block	Good	
West	None		
CEILING	Painted Exposed	Good	
DOOR(s)	Hollow Metal	Fair/Good	
DOOR FRAME(s)	Pressed Metal	Fair/Good	

ROOM NAME STAIR NO. 33

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	Acoustic Mt'l. Panels	Good	
East	Acoustic Mt'l. Panels	Good	
South	None		
West	None		
CEILING	Plaster	Good	
DOOR(s)	None		
DOOR FRAME(s)	None		

ARCHITECTURAL RECONNAISSANCE SURVEY

ROOM NAME STAIR NO. 34

ROOM NO.

ITEM	MATERIAL	CONDITION	REMARKS:
FLOOR	Concrete	Good	
BASE	None		
WALLS:			
North	C.M.U./Acoustic Tile	Good	
East	C.M.U./Acoustic Tile	Good	
South	C.M.U./Acoustic Tile	Good	
West	None		
CEILING	Acoustic Tile	Good	
DOOR(s)	None		
DOOR FRAME(s)	None		

Architectural Reconnaissance Survey

Escalators & Elevators

Kallmann, McKinnell & Wood, Architects, Inc.

ARCHITECTURAL RECONNAISSANCE SURVEY

ITEM: ESCALATORS

MANUFACTURER: OTIS

<u>ESCALATOR NO.</u>	<u>TYPE</u>	<u>SPEED</u>
1	48"	90'/min.
2	48"	90'/min.
3	48"	90'/min.
4	48"	90'/min.

ITEM: ELEVATORS

MANUFACTURER: OTIS

ELEVATOR NO.

<u>ELEVATOR NO.</u>	<u>CAPACITY</u>	<u>SPEED</u>	<u>TYPE</u>
1	75,000 lbs.	50'/min.	Hydraulic
2	30,000 lbs.	50'/min.	Hydraulic
3	15,000 lbs.	50'/min.	Hydraulic
4	8,000 lbs.	100'/min.	Hydraulic
5	8,000 lbs.	100'/min.	Hydraulic
6	2,000 - 2,500 lbs.	150'/min.	Traction

Architectural Reconnaissance Survey

Exterior

Kallmann, McKinnell & Wood, Architects, Inc.

ARCHITECTURAL RECONNAISSANCE SURVEY

EXTERIOR

ITEM	MATERIAL	CONDITION	REMARKS
WALLS:			
North	Granite Glazed Brick Precast Concrete Aluminum Siding	Poor/Good Fair/Good Good Fair/Good	<u>Typical:</u> Granite occurs up to el. 34'-10". Glazed brick and precast concrete are contained between el. 34'-10" and the roof.
East	Granite Glazed Brick Precast Concrete Aluminum Siding	Good Good Good Fair/Good	The aluminum siding occurs at the upper portion of the Auditorium and at enclosing walls of the mechanical spaces located on the roof of the facility.
South	Granite Glazed Brick Precast Concrete Aluminum Siding	Fair/Good Good Good Fair/Good	Stairs at northeast corner have collapsed on one side.
West	Granite Glazed Brick Precast Concrete Aluminum Siding	Fair/Good Fair/Good Good Fair/Good	Brick on relieving angles is pro- truding forward from main face of the wall. Some minor cracking and chipping of granite exists. Generally, the aluminum siding is in good condition but some deter- ioration does exist.
ROOF	Built-Up Roofing	Poor/Fair	The roof is generally very spongy. Flashing and coping are in poor con- dition in several areas. Gravel on roof is almost completely absent in spots. The iron pipe railing around the roof's edge is in poor condition.

7142 083

BACK BAY
B65M
1982

AUTHOR

Hynes Auditorium Expansion

TITLE

Final Rpt (Vol. II-Part A)

DATE
LOANED

BORROWER'S NAME

WOTSC
PUBLIC
LIBRARY



BOSTON PUBLIC LIBRARY



3 9999 06314 463 6

